APPLICATION GUIDE

MIRRACLEAR (Clear Coat) KILLER CAN

How to Apply (Application Steps)

1. Always apply paints in a well-ventilated area, and wear a NIOSH approved respirator to avoid breathing any fumes.
2. Make sure you have good conditions for spraying. The best temperature for spraying this paint, is 75-80 degrees F, and VERY low humidity.
3. Apply 2-3 wet coats of Mirraclear over your existing paint, using steady even passes, from about 6-8 inches away from the substrate, with about 10-15 minutes between coats.
4. Mirraclear will be dry to the touch in about 2-3 hours. Allow 24 hours before handling.